

List of Welding gear and hand tools for Certification Testing

Required for all welders testing:

- 1. Welding Helmet
- 2. Welding Jacket
- 3. Cotton Pants
- 4. Cotton Welding Hat
- Safety Toe Work Boot
- 6. Earplugs
- 7. Safety Glasses
- 8. Clear Face Shield (required for grinding)
- 9. Work Gloves
- 10. Regular vise grip pliers for grabbing hot metal
- 11. Small focused beam LED inspection flashlight

Additional Welding Gear and Hand Tools for SMAW (stick) & Flux Core tests:

- a. Arc Welding Gloves
- b. Slag Hammer
- c. 3 vise-grip C Clamps with pads (one long reach clamp)
- d. One or Two grinders ALL GRINDERS MUST HAVE GUARDS
- a. DEWALT 4-1/2 in 11 Amp Paddle Switch Corded Angle Grinder (DEWALT # 402W5) or similar
- b. DEWALT 7 in 13-Amp Trigger Corded Angle Grinder (DEWALT # DW840) or similar
- e. Grinding wheels
- f. Wire Wheels
- g. MIG Pliers
- h. For pipe specific tests: pipe wedges for fit up, round telescopic mirror for root inspection

Additional Welding Gear and Hand Tools for GTAW (TIG) welding tests:

- i. TIG Welding Gloves
- ii. Tungsten Electrodes
- iii. Collet & Collet Body
- iv. #5, #6 & #7 Size Cups (or other preferred sizes) to fit over the collet body
- v. Small container of Acetone to clean material (not plastic)
- vi. Lint free cloth to clean material
- vii. For pipe or tube tests: Clamps for pipe or tubing

Additional Welding Gear and Hand Tools for GMAW (MIG) welding tests:

- a. MIG pliers
- b. MIG welding gloves
- h. 3 vise-grip C Clamps with pads (one long reach clamp)
- c. Ball Peen Hammer 12 oz. size wood (for light gage sheet metal)
- d. Hand brush
- e. DEWALT 4-1/2 in 11 Amp Paddle Switch Corded Angle Grinder (DEWALT # 402W5) or similar
- f. Wire Wheels